



Trylon

5/8" Dia. x 2-1/2" Long A325 - Update

September 19, 2018

Trylon has recently received notice from an installation crew in Manitoba that in the process of installing the 5/8" x 2-1/2" galvanized A325 bolts on a Trylon tower for Bell that the threads were "stripping". Trylon has identified the lot and heat number of the bolt assemblies supplied and sourced several at our supplier. We were able to install them using the turn of the nut method to the prescribed pretension without issue. Trylon has requested all the damaged bolts returned to Trylon and will send these out, along with new bolt assemblies from the same manufacturing heat and lot, to a third party testing facility to determine the cause of the failures experienced in the field. Once the root cause is determined Trylon will publish their findings and further actions based on results. A caution was made with respect to consequences of "overtightening".

Please contact Trylon's Quality Department if there are any questions regarding this update. (blake.niemi@trylon.com, 519-669-5421 x1265)



Trylon